



Display

Date: **January 14, 2002**

Model: **BVM-D14H1E, BVM-D14H1U**
BVM-D14H5E, BVM-D14H5U

Subject: **TROUBLE WITH H. OUT TRANSISTOR**
WHEN SWITCHING INPUT FORMATS

Serial No: **SEE TEXT**

Italicized information in green applies to Europe, Middle East and Africa.

DESCRIPTION

The H. OUT transistor may not function properly when switching input formats. To correct this condition, perform the following modification procedure.

PARTS REQUIRED

Part No.	Description	Qty.
1-126-961-11	Cap, 2.2 μ F/50V	1
1-216-097-00	Res, Chip, 100 k Ω	1



MODIFICATION PROCEDURE

G Board

1. Replace C1532 with a 2.2 μ F/50V capacitor. (See Figure 1.)
2. Replace R1574 with a 100 k Ω chip resistor. (See Figure 2.)




Figure 1




Figure 2

SERIAL NUMBERS

<i>BVM-D14H1E</i>	<i>2,000,001–2,000,114</i>
BVM-D14H1U	2,000,001–2,000,125
<i>BVM-D14H5E</i>	<i>2,000,001–2,000,041</i>
BVM-D14H5U	2,000,001–2,000,451