SONY

Display

Date: June 12, 2000

Subject: NOISE IN 100% COLOR BAR SIGNAL IN HIGH TEMPERATURE ENVIRONMENT

Model: BKM-41HD, BKM-42HD

Verify picture appears normal.

CONFIRMATION

Broadcast Products

Serial No: 2,500,001–2,500,060 (BKM-41HD) 2,600,001–2,600,246 (BKM-41HD) 2,500,001–2,500,150 (BKM-42HD) 2,600,001–2,600,250 (BKM-42HD)

Technical Bulletin 2000

Worldwide Technical Bulletins for Broadcast and Professional Products

DESCRIPTION

If unit is used in a high temperature environment, noise may appear in the yellow segment of the 100% color bar signal. (See Figure 1.) Noise is easier to view when the monitor is in Blue-Only mode. To correct the symptom, perform the following modification procedure.

NOTE: This symptom may occur in units on which Broadcast Products Technical Bulletin 2000-014 (Modification for Multiple Formats) has been performed.

PARTS REQUIRED

| Part No. | Description | Qty. |
|--------------|---|------|
| 1-216-025-00 | Res, Chip, Metal, 100Ω , $1/10W$ | 1 |
| 4-064-601-01 | Tape, Conductive Fabric (25.4x60mm) | 1 |
| 4-064-601-11 | Tape, Conductive Fabric (25.4x90mm) | 1 |
| 4-064-601-21 | Tape, Conductive Fabric (25.4x150mm) | 1 |
| 4-053-232-01 | Finger, Shield | 1 |




Figure 1

MODIFICATION PROCEDURE

BHD Board (Side B)

- 1. Remove conductive tape from four locations on unit.
- 2. Remove unit cover.
- 3. Remove PWB shield from solder side of board by removing four screws.
- 4. Replace former R33 (0 Ω) with new 100 Ω (1-216-025-11) resistor (zone D-6).
- 5. Reinstall PWB shield.
- 6. Reinstall unit cover.
- 7. Reapply new conductive tape.

DPMO00-026

Page 1 of 1

- Broadcast Professional Products Asia • Sony Australia • Sony Broadcast & Professional Europe • Sony Canada Ltd. • Sony Electronics Inc. USA • Sony Products Professional Latin America