

DisplayDate: **December 9, 1996**Subject: **CORRECTING POOR WHITE BALANCE**Model: **PVM-8040/8041Q/8043MD/8044Q**Serial No: **2,014,501 AND HIGHER (PVM-8040)**
2,508,901 AND HIGHER (PVM-8041Q)
2,000,851 AND HIGHER (PVM-8043MD)
2,505,451 AND HIGHER (PVM-8044Q)**DESCRIPTION**

Flashing or poor white balance in the video picture may be the result of poor insulation between a cathode and a heater in the CRT. To correct this condition, perform the following modification procedure.

NOTE: Refer to Video Products Technical Bulletin 94-088 for related information.

MODIFICATION PROCEDURE

1. Confirm that instructions given in Video Products Technical Bulletin 94-088 have been implemented.
2. Replace the CRT with a new, improved one. (Refer to lot number for appropriate CRT.)

PARTS REQUIRED

Part No.	Description	Qty.
8-737-154-05	<i>For Lot No. 51,101,001 and higher:</i> CRT 09NDX	1
8-737-651-05	<i>For Lot No. 51,018,002 and higher:</i> CRT 09FX	1