

Display

Video Products Technical Bulletin 2001-008

Worldwide Technical Bulletins for Broadcast and Professional Products

Date: January 22, 2001

Subject: IMPROPERLY ADJUSTED 1080/60i AND 1035/60i H BLK

Italicized information in green applies to Europe, Middle East and Africa.

DESCRIPTION

When receiving a 1080/60i or 1035/60i signal, a white vertical band of 2 to 3mm width appears at the left side of monitor in the under-scan mode.

When brightness is increased, it is easily visible. A narrow band of 1mm or less in width is sometimes visible at the right side of monitor.

To correct this condition perform the following adjustment procedure.

ADJUSTMENT PROCEDURE

Re-adjust H. BLK for 1080/60i and 1035/60i, overscan and underscan modes. Perform the "H Blanking Adjustment" procedure in the Service Manual from steps 1 to 13.

Model: BVM-D24E1WE, BVM-D24E1WU

Serial No: 2,000,011–2,000,160 (BVM-D24E1WE) 2,000,196–2,000,300 (BVM-D24E1WU)

DPMO00-047

Page 1 of 1

- Broadcast Professional Products Asia • Sony Australia • Sony Broadcast & Professional Europe • Sony Canada Ltd. • Sony Electronics Inc. USA • Sony Products Professional Latin America