# SONY

## **Display**

**Video Products** Technical Bulletin 19<mark>98</mark> Technical Bulletins for Broadcast and Professional

Products for North, Central, and South America

Subject: PREVENTING CRT PIN DAMAGE, AND ADDING OVER CURRENT PROTECTOR

Date: November 9, 1998

Subject: PVM-96, PVM-97, PVM-136, PVM-137

Serial No: SEE TEXT

### **DESCRIPTION**

#### **Preventing CRT Pin Damage**

The information below affects units with the following serial numbers:

PVM-96 1,000,001-1,004,456 PVM-97 1,000,001-1,011,463

If tension in the wires leading from the C board adds stress to the pins of the CRT, the glass around the pins may crack, causing a short in the CRT pins and the horizontal output (H. OUT) transistor to heat up.

To correct this condition, unlock the purse lock that clamps the wires leading from the C board, to ease the stress on the wires. See Figure 1.




Figure 1

## **Adding Over Current Protector**

The information below affects units with the following serial numbers:

PVM-96	1,004,637 and higher
PVM-97	1,012,284 and higher
PVM-136	1,001,397 and higher
PVM-137	1,004,327 and higher

Because of the short that may occur in the CRT pins as described above, and to protect the H. OUT transistor from failing, resistor R670 (100 $\Omega$ ) on the G2 board (side A) has been removed, and an over current protector circuit has been added to the board, as shown in Figure 2.

The new circuit includes the components listed in Table 1.

Table 1

Part No.	Description	Qty.
1-216-369-00	Res, 1Ω, 2W (R690)	
1-249-414-11	Res, 560Ω,1/4W (R691)	
1-249-433-11	Res, 22kΩ, 1/4W (R692)	
1-249-427-11	Res, 6.8kΩ, 1/4W (R693)	
1-249-431-11	Res, 15kΩ, 1/4W (R694)	1
1-249-438-11	Res, 56kΩ, 1/4W (R695)	
1-249-435-11	Res, 33kΩ, 1/4W (R696)	
8-729-119-76	Transistor, 2SA1175 (Q676)	
8-719-018-72	Thyristor, CR02AM (Q677)	
1-123-875-51	Cap, 10μF/50V (C674, C675)	2
8-719-911-19	Diode, 1SS119 (D673, D674)	2

Page 1 of 2 DPMO98-026, DPMO98-027




Figure 2