Display



WORLDWIDE TECHNICAL BULLETINS FOR BROADCAST AND PROFESSIONAL PRODUCTS

Video Products Technical Bulletin 30-2002-175R2

DATE: June 1, 2009 SUBJECT: POWER AND HOUT TRANSISTOR FAILURE

MODEL: BVM-D9H1A

BVM-D9H1E BVM-D9H1U BVM-D9H5A BVM-D9H5E BVM-D9H5U

SERIAL NO:

BVM-D9H1A	Up to 2,000,027
BVM-D9H1E	Up to 2,000,060
BVM-D9H1U	Up to 2,000,410
BVM-D9H5A	Up to 2,000,025
BVM-D9H5E	Up to 2,000,190
BVM-D9H5U	Up to 2,000,689

Italicized information in green applies to customers outside the United States.

DESCRIPTION

The H OUT transistor may become damaged, resulting in power failure, under the following conditions:

- The BKM-142HD option board is installed.
- The signal cable is pulled out and plugged in, or the signal is cut off after a 720/60p HD-SDI signal is input.

To prevent damage to the transistor, perform the following modification procedure.

PARTS REQUIRED

Part No.	Description	Qty.
MBVMDOS/3	Software V1.17	1
8-719-911-19	Diode, 1SS119	1
1-136-165-00	Cap, 0.1 µF/50V	1
1-247-903-00	Res, 1 $M\Omega$	1
1-107-913-11	Cap, 470 μF	1
8-759-239-34	IC, TC74HC4538AF	1

ORDERING INFORMATION

To order parts online, go to: http://www.sony.com/servicesplus. For service or parts ordering assistance, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 00-1999-000



MODIFICATION PROCEDURE

1. Upgrade software from V1.16 to V1.17.

CAUTION: If the harness that connects the T board (CN801) to the B board (CN301) is too close to the DY, noise may interfere with the H sync signal on the harness, causing the relay to malfunction (chatter). The harness may also pick up an H pulse signal, even though no video signal is input.

To prevent interference, reroute the harness that is folded in the purse lock on the T board side 180°, so that the harness exits the purse lock away from the DY and is 20–30 mm away from the DY.

DPMO02-034R3

P Board (Side B)

2. Replace C554 with a new 470 µF capacitor.

D Board (Side B)

3. Remove C2632 (220 µF), which is soldered in parallel with R2553 (zone B-6).

(See Figure 1.)

- 4. Modify the H SYNC circuit on the D board by adding individual components as follows:
 - a. Remove IC2505 (zone D-7).
 - b. Cut the trace leading from IC2505 pin 3.
 - c. Replace IC2505 with a new IC (TC74HC4538AF).
 - d. Solder the cathode of a new diode (1SS119) to IC2505 pin 3.
 - e. Solder the anode of the diode to the thru-hole on the lower left side of C2583.
 - f. Solder a 0.1 μF capacitor between pins 3 and 8 of IC2505.
 - g. Solder a 1 $M\Omega$ resistor to both leads of the capacitor.




Figure 1

Broadcast Professional Products Asia • Sony Australia • Broadcast Professional Products Europe • Sony Canada Ltd. • Sony Electronics Inc. USA • Sony Broadcast and Professional Latin America