



Display

Date: **September 11, 2000**

Subject: **SOFTWARE UPGRADE—VERSION 1.14**

Model: **BVM-D14H1E, BVM-D14H1U**
BVM-D14H5E, BVM-D14H5U
BVM-D9H1E, BVM-D9H1U
BVM-D9H5E, BVM-D9H5U

Serial No: **SEE TEXT**

Italicized information in green applies to Europe, Middle East and Africa.

DESCRIPTION

Software version 1.14 is now available. The new software offers the following program improvements.

NOTE: This upgrade requires additional modification to the B board.

PARTS REQUIRED

Part No.	Description	Qty.
MBVMDOS/1	BVM-D9H/D14H Series, V1.14	1
1-163-013-11	Cap, 2200pF	2

PROGRAM IMPROVEMENTS

- White balance data at a horizontal frequency of approximately 15kHz (480i/575i) is now independent of white balance data at different horizontal frequencies.
- An error no longer occurs and white balance data is maintained when auto white balance is adjusted at 15kHz (480i/575i).
- ON/OFF tally commands have been added to the serial remote as follows:
 - Tally Light (ON)
 - Serial command 29h (Tally On command)
 - Command Parameter 35h (Tally Red)/36h (Tally Green)
 - Tally Light (OFF)
 - Serial command 2ah (Tally Off command)
 - Command Parameter 35h (Tally Red)/36h (Tally Green)
- White balance data is no longer lost when an external signal is fed after performing auto white balance adjustment.
- In BVM-D9 series, a register limit error no longer occurs when performing auto white balance adjustment.

SERIAL NUMBERS

<i>BVM-D14H1E</i>	<i>2,000,001–2,000,025</i>
BVM-D14H1U	2,000,001–2,000,062
<i>BVM-D14H5E</i>	<i>2,000,001–2,000,040</i>
BVM-D14H5U	2,000,001–2,000,450
<i>BVM-D9H1E</i>	<i>2,000,001–2,000,015</i>
BVM-D9H1U	2,000,001–2,000,335
<i>BVM-D9H5E</i>	<i>2,000,001–2,000,024</i>
BVM-D9H5U	2,000,001–2,000,530

MODIFICATION PROCEDURE

B Board (Side A, Zone C-2)

Replace C2384 and C2385 with new 2200pF capacitors.

UPGRADE INSTALLATION PROCEDURE

1. Load new software:
 - a. Install SRAM card in control panel.
 - b. Turn power switch (in rear) off and on.

NOTE: For BVM-D9 series units, where there is no rear power switch, and for BVM-D14 series units, where rear power switch is inaccessible, restart by selecting SYSTEM CONFIG (2/2) /MAINTENANCE/SYSTEM MENU/RESTART MONITOR. (Extend menu factory password is 1111.)
 - c. Confirm monitor STANDBY LED is blinking slowly (on: 2.5 seconds, off: 0.5 seconds).
 - d. Turn power on from control panel. Version upgrade begins.

NOTE: STANDBY LED will blink rapidly (on: 0.5 seconds, off: 0.5 seconds) during upgrade; upgrade will take approximately 5 minutes to complete.



2. Confirm software version:
 - a. Select STATUS (2/2) menu.
 - b. Verify software version number is correct.
3. Remove SRAM card from control panel.
4. Perform the following adjustment procedure.

ADJUSTMENT PROCEDURE

1. Input 15kHz (480i/575i) and 33kHz (1035i/1080i) signals.
2. If necessary, adjust white balance as per maintenance manual, section 3, "White Balance Adjustment".

ORDERING INFORMATION

NOTE: To order upgrades or for regional service center and parts ordering information, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 001999000

Canadian Customers: Order parts from your usual supplier.