

Figure 2




Figure 3

### SONY

# Video Products Technical Bulletin 94-016

Subject: TREATMENT OF MULTIPLE FAILURE OF

Sony Electronics Inc. Business and Professional Products Group **Technical Publications** 3300 Zanker Road, San Jose, California 95134

**MICRO FUSE** 

#### **Display**

Date: February 28, 1994

Model: PVM-5041Q/8040/8041Q/8044Q

Serial No: 2.002.450 AND LOWER (PVM-5041Q)

2,004,350 AND LOWER (PVM-8040) 2,006,700 AND LOWER (PVM-8041Q) 2,004,500 AND LOWER (PVM-8044Q)

#### **DESCRIPTION**

The micro fuse F1601 (1.25A/125V) on the D board may experience multiple failure in some units. To prevent this condition, perform the following modification procedure.

#### **PARTS REQUIRED**

Part No.	Description	Qty.
1-412-529-11	Inductor, 22μH (L810)	1
1-123-024-21	Cap, Electrolytic, 33μF, 160V (C825)	1
7-322-065-19	Silicon Glue (RTV)	1

#### Additional parts required:

Wire, red (UL1007, AWG 22) 100mm Wire, black (UL1007, AWG 22) 100mm Wire, red (UL1007, AWG 18) 90mm Wire, black (UL1007, AWG 18) 90mm Double-sided adhesive tape

## **MODIFICATION PROCEDURE**

(See Figures 1 through 3.)

- 1. Prepare parts as follows (see Figure 1):
  - Wrap a 100mm wire around each lead of 22µH inductor L810 and solder as shown.
  - Wrap a 90mm wire around each lead of 33µF electrolytic capacitor C825 and solder.
  - Apply double-sided adhesive tape to top of inductor and electrolytic capacitor.

#### D Board, Solder Side

- 2. Cut trace leading from CN503-7 (+B) as shown.
- Remove resist from area near trace cut.
- Solder inductor leads as shown; fix with RTV as shown.

#### P Board, Solder Side

- 5. Secure top of inductor (whose leads were soldered to D board) to board with double-sided adhesive tape (applied in step 1) and RTV.
- 6. Remove resist from area near CN801 as shown in Figure 3.
- 7. Solder positive red wire lead of electrolytic capacitor to trace leading from CN801-7 (+B) and negative black wire lead to trace leading from CN801-1 (E). Affix with RTV.
- Mount 33µF electrolytic capacitor to board in area as shown with double-sided adhesive tape (applied in step 1) and RTV.

NOTE: Capacitor should be 10mm from the flyback transformer.




Figure 1