Display



WORLDWIDE TECHNICAL BULLETINS FOR BROADCAST AND PROFESSIONAL PRODUCTS

Video Products Technical Bulletin 30-2004-134

DATE: July 26, 2004 SUBJECT: HORIZONTAL LINEARITY

MODEL: **PVM-20L5**

PVM-20L5/1 PVM-20L5/2 PVM-20L5/3 PVM-20L5/4 PVM-D20L5A/1 PVM-D20L5A/1

SERIAL NO:

PVM-20L5	2	2,000,001–2,000,81	0
PVM-20L5	/1 2	2,100,001–2,100,10	9
PVM-20L5	/2 2	2,100,110–2,101,10	9
PVM-20L5	/3 2	2,101,110–2,102,54	9
PVM-20L5	/4 2	2,102,550–2,103,28	9
PVM-D20L	.5A 2	2,000,001–2,000,19	1
PVM-D20L	.5A/1 2	2, <i>000,192–2,000,25</i>	6
PVM-D20L	.5A/2 2	2,000,257–2,000,28	6

Italicized information in green applies to customers outside the United States.

DESCRIPTION

A horizontal linearity error may appear in the mid-to-left section of the screen. The horizontal linearity is particularly obvious when the D2 board (1-684-694-11 or -12) is used.

PARTS REQUIRED

Part No.	Description	Qty.
1-411-667-12	Coil	1

Also Required: Sony chemical SC65 RTV (or equivalent)

ORDERING INFORMATION

To order upgrades or for regional service center and parts ordering information, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 001999000

MODIFICATION PROCEDURE

D2 Board

1. Replace L2504 with a new coil, soldering the new coil with the polarities reversed.

NOTE: The coil has three supports. Use diagonal cutters to cut off the unused lead support (which has no winding wire) so that the coil can be soldered with the polarities reversed.

2. Apply RTV to the coil.

DPMO04-021