



Display

Broadcast Products Technical Bulletin 20-2004-142

DATE: July 26, 2004

SUBJECT: UNIT CANNOT BE CONTROLLED

MODEL: ***BVM-D9H5A***
BVM-D9H5E
BVM-D9H5U

DESCRIPTION

If the unit is subjected to an excessive mechanical impact, the bottom plate may become deformed, damaging a diode on the HA board. As a result, the unit cannot be controlled.

SERIAL NO:

BVM-D9H5A *2,000,001–2,000,010*
BVM-D9H5E *2,000,001–2,000,120*
 BVM-D9H5U 2,000,001–2,000,540

Italicized information in green applies to customers outside the United States.

PARTS REQUIRED

Part No.	Description	Qty.
X-4037-184-2	Bottom Cover Assembly	1

ORDERING INFORMATION

To order upgrades or for regional service center and parts ordering information, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 001999000

MODIFICATION PROCEDURE

To prevent inadvertent damage to the bottom plate, replace the bottom cover assembly with a new assembly.

DPM004-024