





Video Products Technical Bulletin 30-2004-096

DATE: June 7, 2004 SUBJECT: DAMAGE TO VIDEO OUTPUT IC

MODEL: **PVM-14L5**

PVM-14L5/1 PVM-14L5/2 PVM-14L5/3 PVM-14L5/4 PVM-20L5 PVM-20L5/1 PVM-20L5/3 PVM-20L5/4 PVM-D14L5A/1 PVM-D14L5A/1 PVM-D14L5A/3 PVM-D14L5A/3 PVM-D20L5/4

PVM-D20L5A/1

PVM-D20L5A/2

DESCRIPTION

The video output IC (IC701, IC702 and/or IC703) on the C board may become damaged.

PARTS REQUIRED

Part No.	Description	Qty.
1-517-712-11	Discharge Gap	1

Also Required: RTV

ORDERING INFORMATION

To order upgrades or for regional service center and parts ordering information, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 001999000

SERIAL NO:

PVM-14L5	2,000,001-2,000,996
PVM-14L5/1	2,100,001-2,100,390
PVM-14L5/2	2,100,391-2,102,040
PVM-14L5/3	2,102,041-2,104,130
PVM-14L5/4	2,104,131-2,104,319
PVM-20L5	2,000,001-2,000,810
PVM-20L5/1	2,100,001-2,100,109
PVM-20L5/2	2,100,110-2,101,109
PVM-20L5/3	2,101,110-2,102,549
PVM-20L5/4	2,102,550-2,102,879
PVM-D14L5A	2,000,001–2,000,054
PVM-D14L5A/1	2,000,055–2,000,346
<i>PVM-D14L5A/2</i>	2,000,347–2,000,466
<i>PVM-D14L5A/3</i>	2,000,467–2,000,549
PVM-D20L5A	2,000,001–2,000,191
PVM-D20L5A/1	2,000,192-2,000,256

Italicized information in green applies to customers outside the United States.

PVM-D20L5A/2 2,000,257-2,000,269

MODIFICATION PROCEDURE

C Board (Side B)

1. Solder a discharge gap between G2 and GND as shown in Figure 1.

NOTE: Maintain a clearance of 1 mm to 7 mm between the discharge gap and the board. Do not allow the discharge gap to touch the board.

- 2. Apply RTV between the discharge gap and the board.
- 3. Perform the modification procedure in Technical Bulletin 30-2003-149 if it has not already been performed.

NOTE: The modification protects the video output IC from damage due to a voltage surge.

DPMO04-001




Figure 1