

Sony Electronics Inc.
 Business and Professional Products Group
 Technical Publications
 3300 Zanker Road, San Jose, California 95134

Display

Date: **September 12, 1994**

Subject: **CORRECTING CRT FLASHING AND
 IRREGULAR WHITE BALANCE**

Model: **PVM-8040/8041Q/8043MD/8044Q**

Serial No: **2,000,001–2,008,300 (PVM-8040)**
2,000,001–2,011,750 (PVM-8041Q)
2,000,001–2,008,100 (PVM-8044Q)
2,000,001–2,000,800 (PVM-8043MD)

DESCRIPTION

A flashing CRT or an irregular white balance in the video picture may be the result of an electrical discharge in the CRT. To correct this condition, a new CRT socket is now available as a replacement part. Perform the modification procedure described below.

MODIFICATION PROCEDURE

**CA Board, Solder Side
 (See Figure 1.)**

1. Replace CRT socket with a new one.
2. Remove R705 and C702.
3. Solder a 15mm jumper on land vacated by R705.
4. Use RTV silicon glue (part no. 7-322-065-19) to secure the CRT socket to the CRT.

Former	→	New
CRT Socket 1-526-958-41	→	CRT Socket 1-251-244-11

NOTE: Units with serial numbers higher than those listed above have CA boards with the new CRT socket factory-installed.




Figure 1