SONY

Display

Date: February 10, 1997

Model: PVM-14N1U/14N2U/20N1U/20N2U

Serial No: 1,000,001–6,002,726 (PVM-14N1U) 1,000,001–6,001,932 (PVM-14N2U) 1,000,001–6,001,212 (PVM-20N1U) 1,000,001–6,000,847 (PVM-20N2U)

DESCRIPTION

After the BKM-104 caption vision board is installed, CAPTION VISION and the OSD may not display. Due to boards and pin assignments being changed, a short circuit may develop between the display timing signal and ground.

NOTE: Only the PVM-14N2U/20N2U versions 1.20 and 1.30 display CAPTION VISION; the PVM-14N1U/ 20N1U versions 1.20 and 1.30 do *not* display the same.

To prevent this situation, perform the following modification procedure during BKM-104 installation.

PARTS REQUIRED

	Part No.	Description	Qty.
	8-719-901-33	Diode, 1SS133	1
	1-216-057-00	Resistor, 2.2k Ω	1
rul -	8-752-877-14	IC CXP85220A-032S V1.40 (IC001)	1

MODIFICATION PROCEDURE

A Board

- 1. Remove rear cabinet cover.
- 2. Remove wire soldered to CN053 pin 17 (zone A-4, side B). (See Figure 1.)
- Remove resist and silk print from around CN053 pin 17. Cut traces.
- 4. Solder removed wire, from CN053 pin 17 (step 2), to CN053 pin 13 as shown in Figure 1.
- 5. Remove JW185 and replace with 1SS133 diode. Solder diode, connecting cathode to IC301 side. (See Figure 2.)
- 6. Replace R318 (10k Ω) with 2.2k Ω resistor.
- 7. Solder 250mm wire jumper between the 1SS133 cathode and CN053 pin 17.

DPMO96-025R

Video Products Technical Bulletin 1996-165R

Technical Bulletins for Business and Professional Products for North, Central, and South America

Subject: BKM-104 BOARD INSTALLATION

NOTE: Route jumper along board edge.

- In the PVM-14N1U/20N1U, verify IC001 is version 1.40. If IC is versions 1.20 or 1.30, replace former IC with new part.
- 9. Remove S board and insert the BKM-104 board.
- 10. Turn power on and enter service mode.
- 11. Double the value which is preset in "No.15 RGB CONT".

NOTE: Value is shown in hexadecimal.

CONFIRMATION

- 1. Confirm that CAPTION VISION displays properly.
- 2. When inputting RGB, confirm that white balance is the same as before modification.
- 3. **NOTE:** If IC301 operating point changes, RGB output balance may change. Readjust white balance, if necessary.

Sony Electronics Inc.

San Jose, California 95134

3300 Zanker Road

V96-223






Figure 1

