



Display

## Video Products Technical Bulletin 30-2004-009

DATE: **January 12, 2004**SUBJECT: **VIBRATION NOISE FROM T501 ON P BOARD**

MODEL: ***BVM-D9H1A***  
***BVM-D9H1E***  
***BVM-D9H1U***  
***BVM-D9H5A***  
***BVM-D9H5E***  
***BVM-D9H5U***

**DESCRIPTION**

A slight vibration noise may resonate from T501 on the P board. The noise occurs if T501 touches R1516.

**MODIFICATION PROCEDURE****P Board (Side A, Zone B-3)**

If noise occurs:

1. Ensure that T501 is 1–2 mm away from R1516.
2. Ensure that R1516 does not touch R511.
3. Apply RTV between T501 and R1516.

SERIAL NO:

*BVM-D9H1A*    *2,000,001–2,000,027*  
*BVM-D9H1E*    *2,000,001–2,000,060*  
 BVM-D9H1U    2,000,001–2,000,503  
*BVM-D9H5A*    *2,000,001–2,000,025*  
*BVM-D9H5E*    *2,000,001–2,000,291*  
 BVM-D9H5U    2,000,001–2,001,071

*Italicized information in green applies to customers outside the United States.*

DPM003-045