



Display

Video Products Technical Bulletin 30-2004-032

DATE: **February 16, 2004**

SUBJECT: **NO PICTURE FROM DAMAGE TO Q613 ON G BOARD**

MODEL: ***BVM-D14H1A***
BVM-D14H1E
BVM-D14H1U
BVM-D14H5A
BVM-D14H5E
BVM-D14H5U

DESCRIPTION

The picture may disappear if Q613 on the G board is damaged and the protection circuit operates.

PARTS REQUIRED

Part No.	Description	Qty.
1-136-165-00	Cap, 0.1 μ F/50V MPS	1

SERIAL NO:

BVM-D14H1A 2,000,001-2,000,155
BVM-D14H1E 2,000,001-2,000,270
 BVM-D14H1U 2,000,001-2,000,312
BVM-D14H5A 2,000,001-2,000,253
BVM-D14H5E 2,000,001-2,000,268
 BVM-D14H5U 2,000,001-2,001,148

Also Required: Sony bond SC608LVZ or equivalent

ORDERING INFORMATION

To order upgrades or for regional service center and parts ordering information, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 001999000

Italicized information in green applies to customers outside the United States.

MODIFICATION PROCEDURE

G Board (Side B, Zone G-2)

1. Solder a 0.1 μ F capacitor between the base of Q613 and the positive (+) side of C585. (See Figure 1.)
2. Affix the capacitor to the board with bond.




Figure 1

DPMO03-055