



Display

Date: **June 7, 1999**

Subject: **VERTICAL FOLD-OVER AT PICTURE TOP**

Model: **OEV143, OEV203, PVM-14M2MDU
 PVM-14M2U, PVM-14M4U, PVM-20M2U
 PVM-20M4U, PVM-20M2MDU**

Serial No: **SEE BELOW**

DESCRIPTION

During normal maintenance or repair, or if a vertical fold-over occurs at the top of picture after many hours of use, perform the modification procedure below.

PARTS REQUIRED

Part No.	Description	Qty
1-124-940-51	Cap, 1 μ F/160V, 105°C high ripple	1

MODIFICATION PROCEDURE

1. Replace C584 (2.2 μ F) with 1 μ F high-ripple capacitor.

NOTE: Since the diameter of this new capacitor is larger than that of the previous capacitor, make sure the C584 capacitor does not touch the Q503 heat sink or the D527 lead wires.

2. Perform the deflection adjustment according to service manual.

Model	Serial Number
OEV143	A800,001–A900,715
OEV203	A800,001–A901,200
PVM-14M2MDU	2,000,001–2,003,200
PVM-14M2U	2,000,001–2,014,050
PVM-14M4U	2,000,001–2,013,050
PVM-20M2U	2,000,001–2,011,200
PVM-20M4U	2,000,001–2,012,150
PVM-20M2MDU	2,000,001–2,005,550