



Display

Broadcast Products Technical Bulletin 20-2004-137

DATE: July 19, 2004

SUBJECT: **MANUAL CORRECTION—ADDITION OF DOUBLE POLE/NEUTRAL FUSING CAUTION**

MODEL: ***BVM-D9H1A***
BVM-D9H1E
BVM-D9H1U
BVM-D9H5A
BVM-D9H5E
BVM-D9H5U
PVM-9L2
PVM-9L2
PVM-9L2//C
PVM-9L3
PVM-9L3


SERIAL NO: ALL

Italicized information in green applies to customers outside the United States.

DESCRIPTION

Correct the following manuals as shown in Figure 1.

- *BVM-D9H1A/D9H1E/D9H1U/D9H5A/D9H5E/D9H5U Maintenance Manual, 1st Edition*
- *PVM-9L2 Service Manual*
- *PVM-9L3 Service Manual*

*Figure 1*

DPM004-018