



Display

Date: **August 10, 1998**

Subject: **ADJUSTMENTS TO PERFORM AFTER
SBX-1602A REPLACEMENT**

Model: **BKM-2080, BKM-2085-14, BKM-2085-20
BKM-2090-14, BKM-2090-20, DMIF-1000
DMIF-2000**

Serial No: **SEE TEXT**

DESCRIPTION

After replacing the SBX-1602A, use the maintenance manual to perform the following adjustments to corresponding models, as shown in Table 1.

Table 1

| Model | Serial No. | Adjustment |
|--------------|---------------------|--|
| BKM-2080 | 2,000,001–2,000,400 | 27MHz Clock PLL Adjustment, Serial Input Part Adjustment |
| BKM-2085-14 | 2,000,001–2,000,770 | 27MHz Clock PLL Adjustment |
| BKM-2085-20 | 2,000,001–2,000,635 | |
| BKM-2090-14 | 2,000,001–2,000,200 | D-2 Serial Signal Input Adjustment (Only adjust the D-2 input frequency) |
| BKM-2090-20 | 2,000,001–2,000,245 | |
| DMIF-1000 | 2,000,001–2,001,700 | D1A Board 27MHz Clock Adjustment |
| DMIF-2000 | 2,000,001–2,000,265 | D2A Board 14.3/17.7MHz Clock Adjustment |