

Display

Date: **May 29, 1995**Subject: **NOISE IN AUDIO AT RGB SPLIT**Model: **PVM-1353MD/1953MD**Serial No: **2,000,001–2,002,250 (PVM-1353MD)**
2,000,001–2,001,400 (PVM-1953MD)**DESCRIPTION**

When RGB SPLIT is selected, noise in the audio signal may occur if audio is part of the RGB signal. To correct this condition, replace IC101 on the A board with a new microcomputer.

PARTS REQUIRED

Part No.	Description	Qty.
8-759-350-77	μPD78013YCW-Y06 V1.1	1