



Display

# Broadcast Products Technical Bulletin 20-2004-143

DATE: July 26, 2004

SUBJECT: D1 H PHASE ADJUSTMENT

MODEL: **BKM-120D**  
**BKM-150CP****DESCRIPTION**

The D1 H phase may not have been adjusted precisely when the units were shipped from the factory.

SERIAL NO:

BKM-120D 2,204,235–2,206,846  
BKM-150CP 2,000,403–2,000,432**ADJUSTMENT PROCEDURE**

1. Confirm the D1 SDI H phase.
2. If the D1 SDI H phase is off to the left, perform the D1 H phase adjustment as described in the appropriate manual.

**NOTE:**

*BKM-120D Maintenance Manual*, 1<sup>st</sup> Edition, page 2-14,  
"3. D1 H Phase Adjustment"

*BKM-150CP Maintenance Manual*, 1<sup>st</sup> Edition, page 1-4,  
"3. H Phase Adjustment"

DPM004-030