

**Display**Date: **October 6, 1997**Subject: **ENHANCING RELIABILITY**Model: **BVM-1315**Serial No: **ALL****DESCRIPTION**

To enhance the reliability of the BVM-1315 color video monitor, replace JW18 (+150V bus, near the EA-5 connector) with an 0.47Ω resistor.

NOTE: Confirm C8 and C10 on the GA board are properly installed. Refer to Broadcast Products Technical Bulletin 94-228.

PARTS REQUIRED

Part No.	Description	Qty.
1-249-443-11	Res, 0.47Ω	1