

Display

Video Products Technical Bulletin 2001-169

Worldwide Technical Bulletins for Broadcast and Professional Products

Date: October 8, 2001

Subject: CAUTION WHEN REPLACING CRT

Model: BVM-D9H1U, BVM-D9H1E, BVM-D9H1A, BVM-D9H5U, BVM-D9H5E, BVM-D9H5A, BVM-8044QD, BVM-8045QD, BVM-9044D, BVM-9045D, PVM-8043MD, PVM-8044Q, PVM-8045Q, PVM-9043MD, PVM-9044PM, PVM-9044QM, PVM-9045PM, PVM-9045QM

Italicized information in green applies to Europe, Middle East and

Serial No: ALL

DESCRIPTION

When replacing the following CRTs, make sure that the pins on the CRT are not bent.

> Description Part No. CRT SD180 8-737-651-05 CRT 09FX (DTV SPEC) 8-737-658-05

CAUTION: If a C board is installed in a CRT with bent pins, the pins may fall off. Use caution when installing the C board to avoid bending the pins on the CRT.

Page 1 of 1 DPMO01-041