



## Video Products Technical Bulletin 30-2016-100

DATE: **October 24, 2016**

SUBJECT: **UNEVEN DISPLAY AFTER PANEL CALIBRATION**

MODEL: ***PVM-X550***  
**PVM-X550**

SERIAL NO: **ALL**

*Italicized information in green applies to customers outside the United States.*

### DESCRIPTION

After performing a panel calibration, the horizontal display may be uneven as indicated by the raster. (See Figure 1.)



*Figure 1*

### COUNTERMEASURE

If the display is uneven, perform the panel calibration again.

---

#### **NOTE:**

- If the CALIBR. indicator is not lit or the "Recommend Calibration" message is not indicated, panel calibration can be performed from:
    - System Setting menu > Calibr. button, or
    - 0 button of the SONY monitor control unit,Refer to the operating instructions.
  - While panel calibration is being performed:
    - Do not wipe dirt off the monitor.
    - Do not touch the monitor.
- 

DPMO16-017