

**Display**Date: **March 1, 1999**Subject: **C532 REPAIR DUE TO PHYSICAL SHOCK**Model: **CHM-1343MD, PVM-1340, PVM-1341**
PVM-1342Q, PVM-1343MD, PVM-1344QSerial No: **ALL****DESCRIPTION**

If unit experiences physical shock, the traces or area surrounding T501 on the A board may be damaged. If this happens, replace capacitor C532 with a new one and repair any damaged traces in the T501 area.

If A board itself is damaged, replace it with a new board.