

**Display**Date: **October 15, 2001**Model: **PHM-14M8U, PHM-20M8U, PVM-20M7MDE**Subject: **CRACKED SOLDER AT ELECTROLYTIC
CAPACITORS ON G BOARD**Serial No: **UP TO 2,000,185 (PHM-14M8U)**
UP TO 2,000,275 (PHM-20M8U)
UP TO 2,003,464 (PVM-20M7MDE)*Italicized information in green applies to Europe, Middle East and Africa.***DESCRIPTION**

If solder cracks at the electrolytic capacitors on the G board, add solder to the following capacitors.

- C637 (330/160)
- C626 (4700/35)