



Display

Video Products Technical Bulletin 30-2003-097

DATE: **March 24, 2003**SUBJECT: **COVER ON CARRYING HANDLE CRACKS**

MODEL: **BVM-D9H1A**
BVM-D9H1E
BVM-D9H1U
BVM-D9H5A
BVM-D9H5E
BVM-D9H5U

DESCRIPTION

The cover on the carrying handle may crack, depending on operating conditions. If the unit continues to be used, the cover may eventually break, exposing the metal core inside the handle.

To correct or prevent this condition, replace the cabinet assembly with a new assembly.

SERIAL NO:

BVM-D9H1A 2,000,001 and Higher
BVM-D9H1E 2,000,001 and Higher
 BVM-D9H1U 2,000,001 and Higher
BVM-D9H5A 2,000,001 and Higher
BVM-D9H5E 2,000,001 and Higher
 BVM-D9H5U 2,000,001 and Higher

Italicized information in green applies to customers outside the United States.

PARTS REQUIRED: BVM-D9H1 SERIES

Part No.	Description	Qty.
X-4037-295-5	Cabinet Assembly	1

PARTS REQUIRED: BVM-D9H5 SERIES

Part No.	Description	Qty.
X-4037-296-5	Cabinet Assembly	1

ORDERING INFORMATION

To order upgrades or for regional service center and parts ordering information, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin *001999000*

DPMO02-054