



Display

Video Products Technical Bulletin 30-2003-138

DATE: **July 7, 2003**SUBJECT: **READJUSTMENT OF DEFLECTION CIRCUIT
(1080/48i)**MODEL: **PVM-14L5/1**
PVM-20L5/1
PVM-D14L5A/1
PVM-D20L5A

SERIAL NO:

PVM-14L5/1 2,100,001-2,100,195
PVM-20L5/1 2,100,001-2,100,059
PVM-D14L5A/1 2,100,001-2,100,161
PVM-D20L5A 2,100,001-2,100,121

Italicized information in green applies to customers outside the United States.

DESCRIPTION

Units sold outside the United States may require a readjustment of the deflection circuit (1080/48i).

To readjust the deflection circuit:

1. Input a 1080/48i cross-hatch signal.
2. Perform the following adjustments as described in the service manual:
 - a. H blanking adjustment (section 2-8)
 - b. Linearity adjustment (section 2-9)

NOTE: Units sold in the United States have already been adjusted.

DPM003-009