



# Broadcast Products Technical Bulletin 20-2008-093

DATE: May 12, 2008

SUBJECT: **HARDWARE CHANGES INCLUDED WITH  
VERSION 1.1 SOFTWARE**MODEL: **BVM-L230/1****DESCRIPTION**

SERIAL NO:

With the introduction of software V1.1, hardware in the monitor is modified as follows:


BVM-L230/1 2,000,127 and Higher

- The location of the ST1 board is changed to reduce impact to the temperature sensor with fluctuating set conditions. (See Figure 1.)
- The LVDS harness is routed differently to improve operation. (See Figure 2.)

These hardware modifications will be reflected in the revised version of the *BVM-L230 Service Manual*, 1<sup>st</sup> Edition.

**LOCATION OF ST1 BOARD**


The new location of the ST1 board is as shown in Figure 1.

**Figure 1**

DPMO07-069

## ROUTING OF LVDS HARNESS

The LVDS harness is routed as shown in Figure 2.



*Figure 2*