Display



WORLDWIDE TECHNICAL BULLETINS FOR BROADCAST AND PROFESSIONAL PRODUCTS

Video Products Technical Bulletin 30-2009-040

DATE: March 30, 2009 SUBJECT: FIRMWARE UPGRADE—VERSION 1.40

MODEL: FWD-50PX3/BK

FWD-50PX3/BZ FWD-50PX3/SK FWD-50PX3/SK1 FWD-50PX3/SZ

SFRIAL NO: ALL

DESCRIPTION

Firmware version 1.40 is available.

ORDERING INFORMATION

This upgrade requires specialized equipment. Sony regional service centers are available to perform the upgrade. To contact your Sony service center, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 00-1999-000

PROGRAM IMPROVEMENT

VIDEO OUT and AUDIO OUT are now correctly synchronized with respect to input when changed under the following conditions:

- Two analog option boards (BKM-FW10, FW11, or FW12) are installed to option slots 1 and 2 of FWD-50PX3.
- Input is switched between Option1 and Option2 using the S-Video (Video) or Option keys on the remote commander.

Previously, when video was switched to input (1 or 2), audio remained in the original input (2 or 1). For example VIDEO OUT was Option1, but AUDIO OUT was Option2.

DPMO08-048