Date: **August 2, 1999**

Subject: **SOFTWARE UPGRADE—VERSION V1.33**

Model: **BVM-14E1U, BVM-14E5U, BVM-14F1U**
BVM-14F5U, BVM-20E1U, BVM-20F1U

Serial No: **ALL**

DESCRIPTION

V1.33 software is now available. The new software implements the following program improvements.

PARTS REQUIRED

Part No.	Description	Qty.
MBVMOS/03	Software Upgrade Kit	1

PROGRAM IMPROVEMENTS

- Operation of the control panel rotary encoders has been improved. Previously, data might jump when the encoders were adjusted.

- After the monitor's main power is cycled, the Remote-2 On/Off setting (in Setup menu) is no longer reset to OFF; the settings are now saved and cycling does not affect Remote-2 setting.

- The accuracy of the internal signal generator xy chromaticity coordinate values was increased.

ADJUSTMENT PROCEDURE

1. Execute /SETUP…/EXTEND MENU/ADJ INT SIGNAL menu.

2. Execute /CONTROL PRESET ADJ…/AUTO MENU for each input format used

3. Perform STD color temperature adjustment.

NOTE: If COL1 and COL2 are utilized, perform color temperature adjustment.

EM99-1010

Page 1 of 1

Broadcast Professional Products Asia · Sony Australia · Sony Broadcast & Professional Europe · Sony Canada Ltd. · Sony Electronics Inc.USA · Sony Products Professional Latin America

2019990626W01.FM