SONY®

Broadcast Products
Technical Bulletin 96-155

Sony Electronics Inc.
Business and Professional Products Group
Technical Publications
3300 Zanker Road, San Jose, California 95134

Display

Date: **July 29, 1996**

Model: **BKM-2085-14/20**
BKM-2090-14/20

Serial No: **ALL**

Subject: **CAUTION IN INSERTING BA3 BOARD INTO SLOT**

DESCRIPTION

The BA3 board will break if it is not correctly inserted into the monitor slot as described in the Operation and Maintenance Manual, section 1-2, paragraph 4 "Mounting the BA3 Board," and as detailed below.

BA3 BOARD INSTALLATION

1. Insert BA3 board into BA slot with component side facing rear of monitor as shown in Figure 1.

2. Confirm that BA3 label is affixed on finger hook and appears as shown in Figure 1, inset.

REAR OF MONITOR

COMPONENT SIDE

LABEL IS SHOWN AS IT APPEARS ON FINGER HOOK

BA3

FINGER HOOK

BA3 BOARD

Figure 1