

Display

Date: **August 26, 1996**Subject: **SLR-103A INSTALLATION ASSIST KIT**Model: **PVM-20N1U/20N2U**Serial No: **ALL****DESCRIPTION**

New drive nuts are required to reinstall the SLR-103A slide rail when replacing a unit in AIE mount rack. Drive nuts used for mounting SLR-103A on the rack mount are not designed to be removed. They are designed for attaching and screwing slide rail into position permanently.

New drive nuts for the SLR-103A are packed in an Assist Kit which must be ordered to reinstall the unit.

PARTS REQUIRED

Part No.	Description	Qty.
X-4032-990-1	Assist Kit	1

NOTE: The Assist Kit is required to reinstall SLR-103A.

