Display



WORLDWIDE TECHNICAL BULLETINS FOR BROADCAST AND PROFESSIONAL PRODUCTS

Video Products Technical Bulletin 30-2005-020

DATE: April 4, 2005

SUBJECT: REPLACE CRT CAUTION LABEL

MODEL: PVM-9L2//C1

PVM-9L2/5 PVM-9L2/5

SERIAL NO:

PVM-9L2//C1 6,000,396-6,000,625 PVM-9L2/5 2,500,217-2,500,276 PVM-9L2/5 2,013,384-2,015,504

Italicized information in green applies to customers outside the United States.

DESCRIPTION

CRTs with the new DARK_TINT panel material (8-737-154-05) should have a corresponding CRT caution label, which lists the new model name of the CRT.

Confirm that the correct caution label is attached as follows:

- 1. Remove the cabinet.
- 2. If the CRT model shown on the CRT caution label inside the top cabinet is incorrect, attach a new CRT caution label over the existing label.

PARTS REQUIRED

Part No.	Description	Qty.
4-035-053-31	CRT Caution Label	1

ORDERING INFORMATION

To order upgrades or for regional service center and parts ordering information, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 001999000

DPMO04-054