


# Capacitors A600



C214	10 $\mu\text{F}$ - 25v
C235	100 $\mu\text{F}$ - 25v
C236	100 $\mu\text{F}$ - 25v
C237	470 $\mu\text{F}$ - 16v
C239	100 $\mu\text{F}$ - 25v
C303	22 $\mu\text{F}$ - 25v
C304	22 $\mu\text{F}$ - 25v
C306	10 $\mu\text{F}$ - 25v
C307	470 $\mu\text{F}$ - 16v
C324	22 $\mu\text{F}$ - 25v
C334	22 $\mu\text{F}$ - 25v
C408	1000 $\mu\text{F}$ - 10v
C409	100 $\mu\text{F}$ - 25v
C459	22 $\mu\text{F}$ - 25v
C460	10 $\mu\text{F}$ - 25v
C613	10 $\mu\text{F}$ - 25v
C811	1000 $\mu\text{F}$ - 10v
C821	47 $\mu\text{F}$ - 16v
C822	47 $\mu\text{F}$ - 16v

C304 don't have the same voltage position  
on rev 1.3 and 1.5

(rev 2B)