



Display

Video Products Technical Bulletin 30-2002-050

DATE: **May 13, 2002**SUBJECT: **SAVE L506 FROM FORMER A BOARD FOR
MOUNTING ON NEW A BOARD**

MODEL: **PVM-1340**
PVM-1341
PVM-1342Q
PVM-1344Q
PVM-1343MD
PVM-1440QM
PVM-1442QM
PVM-1444QM
PVM-1443MD

DESCRIPTION

L506 (micro-inductor, 3.9 mH, 1-408-238-00) is no longer available as an individual component, and new A boards (A-1296-520-A) no longer contain L506 (side A, zone B-2).

Therefore, when replacing the A board, remove L506 from the former A board and mount it on the new A board.

SERIAL NO: **ALL**

Italicized information in green applies to customers outside the United States.

DPMO01-060