

**Display**

Date: **October 2, 1995**

Subject: **REPLACEMENT DIODE RGP30K**

Model: **PVM-95/96/97/135/136/137**



Serial No: **SEE TEXT**

**DESCRIPTION**

An improved diode, RGP30K, now replaces former damper diode FR304 (8-905-661-01). The new part number is:

**8-719-027-56**



Table 1 gives applicable serial numbers.

**Table 1**

Model	Serial No.
PVM-95	1,000,001–1,005,418 1,300,001–1,300,380
PVM-96	1,000,001–1,001,300 1,300,001–1,300,280
PVM-97	1,000,001–1,002,400
PVM-135	1,000,001–1,001,550 1,300,001–1,300,150
PVM-136	1,000,001–1,000,720 1,300,001–1,300,070
PVM-137	1,000,001–1,001,000

**REPLACEMENT PROCEDURE**

**900A Board (Solder Side)**

Replace former diodes as shown in Table 2:

**Table 2**

Model	Serial No.
PVM-95 PVM-135	D410
PVM-96 PVM-97 PVM-136 PVM-137	D512