



Display

Video Products Technical Bulletin 30-2004-132

DATE: July 26, 2004

SUBJECT: SERVICE DATA CHANGE FROM SOFTWARE
UPGRADE

MODEL: PVM-14L2MD/2
PVM-20L2MD/2
PVM-20L2MD/2

DESCRIPTION

Software for the units listed in this bulletin have already been upgraded from V2.1 to V2.2. (You can confirm the version in Service mode under SYSTEM.)

SERIAL NO:

PVM-14L2MD/2 2,001,001 and Higher
PVM-20L2MD/2 2,003,411 and Higher
PVM-20L2MD/2 2,500,033 and Higher

As a result of the upgrade, service data is changed as follows (when a composite video signal with burst is input):

Service mode: SIGNAL > DECODER COLOR > DEC LPF

Version	Data
2.1	0
2.2	1

Italicized information in green applies to customers outside the United States.

NOTE: V2.1 allows you to change DEC LPF values within a range in Service mode; however, turning power OFF and ON returns the values to those set before the change.

DPM004-028