

WORLDWIDE TECHNICAL BULLETINS FOR BROADCAST AND PROFESSIONAL PRODUCTS

Video Products Technical Bulletin 30-2013-133

DATE: October 21, 2013

MODEL: PVM-2541 PVM-2541 PVM-2541A PVM-2541A

SERIAL NO: ALL

Italicized information in green applies to customers outside the United States.

DESCRIPTION

Correct the following manual as shown in Figure 1.

SUBJECT: MANUAL CORRECTION-OB BOARD

PART NUMBER

PVM-2541, PVM-2541A Service Manual, 1st Edition (*Revised 2*)

NOTE: Add the items in red.

5-5 SECTION 5 SPARE PARTS 5-2. EXPLODED VIEWS CHASSIS BLOCK			
No.	Part No.	SP	Description
106	1-895-004-11	s	MOUNTED CIRCUIT BOARD, QB (for PVM-2541) (S/N 3000001 to 3100000 (SY)) (S/N 7000001 to 7099999 (SY)) (S/N 5000001 to 5100000 (CN))
	1-895-004-41	S	MOUNTED CIRCUIT BOARD, QB (for PVM-2541) (S/N 3100001 and higher (SY)) (S/N 5100001 and higher (CN))
	1-895-004-81	S	MOUNTED CIRCUIT BOARD, QB (for PVM-2541A) (S/N 3000001 and higher (SY)) (S/N 5000001 and higher (CN))

Figure 1

DPMO13-014

Broadcast Professional Products Asia • Sony Australia • Broadcast Professional Products Europe • Sony Canada Ltd. • Sony Electronics Inc. USA • Sony Broadcast and Professional Latin America