



Video Products Technical Bulletin 30-2004-129

DATE: July 19, 2004

SUBJECT: WHITE BALANCE ADJUSTMENT FOR MZ CRT

MODEL: **PVM-14L5**
PVM-20L5
PVM-D14L5A
PVM-D20L5A

DESCRIPTION

A new white balance adjustment value is required for monitors that have the new MZ-type CRT instead of the MT-type CRT. Use the new value as shown in the following manual correction.

SERIAL NO:
 PVM-14L5 2,102,041 and Higher
 PVM-20L5 2,101,110 and Higher
PVM-D14L5A 2,000,347 and Higher
PVM-D20L5A 2,000,192 and Higher

MANUAL CORRECTION

Correct the white balance adjustment value in the *PVM-14L5 Service Manual* (Rev. 1) as shown in Figure 1.

Italicized information in green applies to customers outside the United States.




Figure 1

NOTE: Use the new white balance adjustment value whenever you replace the CRT with an MZ-type CRT, even in units with serial numbers other than those listed in this bulletin.