



Display

Video Products Technical Bulletin 30-2003-001

DATE: **January 8, 2003**SUBJECT: **REUSE L506 WHEN REPLACING THE A BOARD**

MODEL: **PVM-1942Q**
PVM-1943MD
PVM-1944Q
PVM-2042QM
PVM-2043MD
PVM-2044QM

SERIAL NO: **ALL**

Italicized information in green applies to customers outside the United States.

DESCRIPTION

The micro-inductor mounted on the A board is no longer available. When replacing the board, reuse the micro-inductor from the previous board.

MODIFICATION PROCEDURE

Remove L506 (3.9 mH micro-inductor) from the former A board and mount it on the new A board.




Figure 1

DPM002-015