



# Video Products Technical Bulletin 30-2009-116

DATE: July 13, 2009

SUBJECT: **MANUAL CORRECTION—FOOT ASSEMBLY (A)  
AND FOOT ASSEMBLY (B) IN CABINET BLOCK 2**

MODEL: **BVM-L230  
BVM-L230/1  
BVM-L230/2  
BVM-L230/3  
BVM-L230/4**

SERIAL NO: **ALL**

## DESCRIPTION

Correct the following manual as shown in Figure 1.

*BVM-L230 Service Manual, 1<sup>st</sup> Edition (Rev. 2)*




Figure 1

DPMO09-007