Display



WORLDWIDE TECHNICAL BULLETINS FOR BROADCAST AND PROFESSIONAL PRODUCTS

Video Products Technical Bulletin 30-2005-002R

DATE: March 21, 2005 SUBJECT: MODIFICATION REQUIRED WHEN REPLACING CRT WITH NEW CRT

MODEL: **PVM-9L2**

PVM-9L2 PVM-9L2/1 PVM-9L2/1 PVM-9L2/2 PVM-9L2/3

PVM-9L2/3 PVM-9L2/4 PVM-9L2/4 PVM-9L2/7C PVM-9L2/7C1

SERIAL NO:

PVM-9L2	All
PVM-9L2	All
PVM-9L2/1	All
PVM-9L2/1	All
PVM-9L2/2	All
PVM-9L2/2	All
PVM-9L2/3	All
PVM-9L2/3	All
PVM-9L2/4	<i>Up to 2,500,216</i>
PVM-9L2/4	Up to 2,013,383
PVM-9L2/7C	All
PVM-9L2/7C1	<i>Up to 2,800,395</i>

Italicized information in green applies to customers outside the United States.

DESCRIPTION



When you replace the CRT (DARK_TINT panel, 8-737-154-05) with a new CRT (TINT panel, 8-737-154-15), replace circuit components on the B board as follows.

NOTE: The modification is required because of a change in the transparency ratio between the CRTs. The modification is not required if you replace the CRT with the same type of CRT.

PARTS REQUIRED

	Part No.	Description	Qty.
	1-218-717-11	Res, Chip, 1608, 11 $k\Omega$	1
	1-216-822-11	Res, Chip, 1608, 1.2 kΩ	1
0	4-035-053-31	CRT Caution Label	1



ORDERING INFORMATION

To order upgrades or for regional service center and parts ordering information, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 001999000

MODIFICATION PROCEDURE

B Board

- 1. Replace R292 (side A, zone C-4, 10 k Ω ABL constant) with a new 11 k Ω resistor.
- 2. Replace R374 (side B, zone D-3, 1.8 k Ω SUB CONTRAST) with a new 1.2 k Ω resistor.



3. Attach the new CRT caution label inside the top cabinet over the existing label.

The new label lists the model name of the new CRT.

DPMO04-044R