

Display

Video Products Technical Bulletin 2000

Worldwide Technical Bulletins for Broadcast and Professional Products

Date: November 13, 2000

Subject: REPLACE SCREWS SECURING AC IN

SOCKET TO MOUNT AC PLUG HOLDER

Model: BVM-8045QD, BVM-9045D, PVM-5041Q PVM-6041QM, PVM-8040, PVM-8042Q PVM-8045Q, PVM-9040ME, PVM-9042QM

PVM-9045QM, SSM-9040P

Serial No: SEE TEXT

Italicized information in green applies to Europe, Middle East and

DESCRIPTION

AC plug holder "A" cannot be mounted to the AC IN socket using the short screws securing the AC IN socket.

To mount AC plug holder "A", replace the two screws securing the AC IN socket with either of the following screws.

PARTS REQUIRED

| Part No. | Description | Qty. |
|------------------------------------|--|------|
| 3-178-213-21 or 3-178-213-31 | Screws, +B3x10, black or Screws, +B3x12, black | 2 |

SERIAL NUMBERS

| BVM-8045QD | 2,001,976-2,002,235 |
|------------|---------------------|
| BVM-9045D | 2,002,701–2,003,300 |
| PVM-5041Q | 2,509,371-2,509,720 |
| PVM-6041QM | 2,510,101–2,510,345 |
| PVM-8040 | 2,030,711-2,031,710 |
| PVM-8042Q | 2,011,501-2,012,900 |
| PVM-8045Q | 2,005,431-2,006,830 |
| PVM-9040ME | 2,019,051–2,019,350 |
| PVM-9042QM | 2,008,001–2,009,900 |
| PVM-9045QM | 2,002,881–2,003,430 |
| SSM-9040P | 2,006,701–2,006,920 |
| | |

Page 1 of 1 DPMO00-041