

**Display**

Date: **March 30, 1998**Subject: **PART CHANGE—MICRO FUSE F654**Model: **PVM-3230**Serial No: **ALL****DESCRIPTION**

A different part is now available as replacement for fuse F654 (3.15A/125V, 1-532-781-21) on the FA board.

Use the following part number when ordering:

Micro Fuse 4A
1-532-782-11