SONY

Video Products Technical Bulletin 95-113

Subject: ABORTED SCREEN MENU SETTING

Sony Electronics Inc. Business and Professional Products Group Technical Publications 3300 Zanker Road, San Jose, California 95134

Display

Date: August 21, 1995

Model: PVM-1353MD/1953MD

Serial No: **2,000,001–2,000,500**

DESCRIPTION

When turning power on and off after performing a screen menu setting, the setup data may not be properly stored in system memory. To ensure communication between the main CPU and a sub-CPU at power on, resolder C1202 ($1\mu F$) on the M board.