

WORLDWIDE TECHNICAL BULLETINS FOR BROADCAST AND PROFESSIONAL PRODUCTS

## Video Products Technical Bulletin 30-2002-134

Display

**DATE: August 5, 2002** 

SUBJECT: VIDEO OR RASTER DOES NOT APPEAR

MODEL: **PVM-14L5** 

**PVM-20L5** 

SERIAL NO:

PVM-14L5 2,000,001-2,000,767 PVM-20L5 2,000,001-2,000,610 **DESCRIPTION** 

If the connectors attaching the D1 board to the D board are not securely connected, video or raster does not appear.

## **MODIFICATION PROCEDURE**

## **D1** Board

Press the following connectors firmly back in place:

- CN1501
- CN1502
- CN1503

DPMO02-025