

Sony Electronics Inc.
Business and Professional Products Group
Technical Publications
3300 Zanker Road, San Jose, California 95134

Display

Date: **December 12, 1994**

Subject: **MANUAL CORRECTION—C811 PART NUMBER**

Model: **PVM-91**

Serial No: **ALL**

DESCRIPTION

Correct the PVM-91 Service Manual as shown in Figure 1. When replacing C811 on the D board, use a capacitor with the correct part number.

No.	Part No.	Description
C811	4-123-908-00	ELECTROLYTIC CAPACITOR, 4.7 μ F/25V
	1-110-674-11	

Figure 1