

DisplayDate: **December 9, 1996**Subject: **PART REPLACEMENT**Model: **PVM-14N1U/14N2U, SSM-14N1U**Serial No: **6,003,584 AND HIGHER (PVM-14N1U)**
6,002,320 AND HIGHER (PVM-14N2U)
6,002,572 AND HIGHER (SSM-14N1U)**DESCRIPTION**

As a preventive measure in the event of the rare possibility of a short circuit occurring between the emitter and collector of Q551, replace resistor R561 (8.2 Ω) with a new 0.25A circuit protector (IC link).

PARTS REQUIRED

Part No.	Description	Qty.
1-532-727-91	Circuit Protector 0.25A	1

