





## Broadcast Products Technical Bulletin 20-2004-257

DATE: December 20, 2004 SUBJECT: MANUAL CORRECTION—CAPACITORS ON D
BOARD

MODEL: **BVM-D9H1A** 

BVM-D9H1A/1 BVM-D9H1A/2 **BVM-D9H1E** BVM-D9H1E/1 BVM-D9H1E/2 BVM-D9H1E/3 **BVM-D9H1U** BVM-D9H1U/1 BVM-D9H1U/2 **BVM-D9H5A** BVM-D9H5A/1 BVM-D9H5A/2 **BVM-D9H5E** BVM-D9H5E/1 BVM-D9H5E/2 BVM-D9H5E/3 BVM-D9H5U BVM-D9H5U/1 BVM-D9H5U/2

SERIAL NO: ALL

Italicized information in green applies to customers outside the United States.

## DESCRIPTION

Correct the following manual as shown in Figures 1 and 2. BVM-D9H Series Maintenance Manual, 1st Edition




Figure 1

DPMO04-038




Figure 2