

**Display**

Date: **January 6, 1997**Subject: **FLASHING, POOR WHITE BALANCE IN
5-INCH CRT**Model: **PVM-5041Q**Serial No: **1,000,001–2,007,750****DESCRIPTION**

The insulation between cathode and heater in the 5-inch CRT may deteriorate, resulting in flashing or poor white balance. To correct this condition, replace the CRT with a new one.

CRT 06JV **8-733-921-05**